



BMW 3: 1JRF256

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber: | WBA3D91090F407359 | Versionname: | 3 BER 316d 116PK |
| First Registrationdate: | 5/02/2015 | Fiscalpower: | |
| Expertise Mileage: | 119955 | Power Kw: | 85 |
| Bodytype: | Berline | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3812 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Rear parking sensors | |
| GPS storage | HD | Type of Tow bar | No Tow bar |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 225/50/17/94 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
| | Re.L. | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|-------------------|----------------|
| Total cost ex VAT | 1766,05 |
|-------------------|----------------|

| | |
|--------------------------------|-------------|
| Ignition key, Worn, Acceptable | 0,00 |
|--------------------------------|-------------|



| | |
|-----------------------------------|------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display


| | |
|---------------------------------------|------|
| Bonnet, Chemical polution, Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

| | |
|---|------|
| Door F R, Dent(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---------------------------------------|------|
| Windscreen, Stone chip(s), Acceptable | 0,00 |
|---------------------------------------|------|



| | |
|---|--------|
| Roof, Chemical polution, LI - Repair and paint (complete) | 481,50 |
|---|--------|



| | |
|---|--------|
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |
|---|--------|



| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---------------------------------|--------|
| Foglight L, Broken, E - Replace | 138,00 |
|---------------------------------|--------|



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display