



BMW 2 ACTIVE TOURER: 1JTK229

Vinnumber:	WBA2C11050VZ56126	Versionname:	2.0 218D (100KW) ACTIVE TOURER
First Registrationdate:	20/02/2015	Fiscalpower:	
Expertise Mileage:	68347	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2513
Maintenance:	29000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 W LightMetal				
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 8 mm	Re.R.	Vredestein: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	583,32
-------------------	---------------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00



Rearlight R, Crack, E - Replace

114,00



Wing R L, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), Acceptable

0,00



Backrest cover F R, Scratch(es), Smart repair

64,32



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover R, Stain, Cleaning

25,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), Acceptable

0,00

