



**AUDI A1 SPORTBACK: 1LBB707**

Vinnumber:	<b>WAUZZZ8X2GB020538</b>	Versionname:	<b>1.6 TDI 85KW</b>
First Registrationdate:	<b>6/08/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>61225</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1231</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/60/15/88 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 7 mm</b>	Fr.R.	<b>Pirelli: 7 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1024,80</b>
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Bad repair, Acceptable

0,00



Luggage space cover, Missing, E - Replace

192,00



Ignition key, Missing, E - Replace

150,00



SD card, Missing, E - Replace

220,00




Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Dent(s), PDR - Paintless dent repair

82,80




Door R R, Bad repair, Acceptable

0,00



Door F R, Bad repair, Acceptable

0,00



Roof, Scratch(es), 67 - Polish

0,00

No pictures to display