



AUDI A7 SPORTBACK: 1KV653

Vinnumber:	WAUZZZ4G5GN036091	Versionname:	2.0 TFSI S TRONIC DCT
First Registrationdate:	16/07/2015	Fiscalpower:	
Expertise Mileage:	153538	Power Kw:	185
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2309
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/40/19/100 V LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment


Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	2043,58
-------------------	----------------

Wing R L, Scratch(es), 67 - Polish	0,00
------------------------------------	-------------

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair	122,40
--	---------------



Trunk lid covering R, Hole, E - Replace

4,52



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Tyre repair kit, Missing, E - Replace

252,64



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

465,84





Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s), LI - Repair and paint (complete) 430,02



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door trim F L, Scratch(es), E - Replace 132,00



Bodywork, Chemical pollution, 67 - Polish 192,00





Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Acceptable	0,00
<i>No pictures to display</i>	