



**FORD TRANSIT COURIER: 1TPV969**

Vinnumber:	<b>WF0WXXTACWHD60847</b>	Versionname:	<b>1.5 TDCi 56kW Trend</b>
First Registrationdate:	<b>9/01/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>182514</b>	Power Kw:	<b>56</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4716</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Rear parking sensors	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/60/15/88 H Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>1961,94</b>
-------------------	----------------

Rear floor , Deformed / Strained, Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>303,15</b>
---	---------------



Wheel cover F L, Missing, E - Replace

22,50




Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Windscreen, Stone chip(s), Acceptable

0,00



Spare wheel, Missing, E - Replace

153,60



Wheel cover F R, Missing, E - Replace

22,50



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*

Dashboard, Hole, Smart repair

110,64



Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Door panel R R, Broken, E - Replace

91,50



Trunk door R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wheel cover R R, Missing, E - Replace

22,50



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02





Wheel cover R L, Missing, E - Replace

22,50



Ignition key, Missing, E - Replace

150,00

*No pictures to display*