



PEUGEOT 2008: 1KKF350

Vinnumber:	VF3CU8HR0FY051850	Versionname:	1.4 HDI 50KW ACTIVE
First Registrationdate:	19/05/2015	Fiscalpower:	
Expertise Mileage:	1	Power Kw:	50
Bodytype:		Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	No	Parking lot:	515
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	NOT OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Panoramic roof
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	No
Tires wear profile	NOT OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	NOT OK	Wiper fluid level	NOT OK
Handbrake	NOT OK	Transmission	NOT OK
		Lighting	NOT OK
		Wiperblades	NOT OK

Degree of wear

195/60/16/89 H LightMetal				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Total cost ex VAT	2045,95
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00





Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Bonnet, Dent(s), Acceptable

0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Luggage space cover, Missing, E - Replace

240,00



Roof pillar R, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), Acceptable

0,00



Bumper corner R L, Scratch(es), It - Spot repair

115,56



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Interior, Dirty, Cleaning

200,00



Bumper corner R R, Scratch(es), Le - Replace and paint

190,51



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00





Bumper R, Scratch(es), Acceptable

0,00

