



**BMW 3: 1JNF285**

|                                    |                                     |              |                             |
|------------------------------------|-------------------------------------|--------------|-----------------------------|
| Vinnumber:                         | <b>WBA3K91000F936740</b>            | Versionname: | <b>3 TOURING 316d 116PK</b> |
| First Registrationdate:            | <b>23/01/2015</b>                   | Fiscalpower: |                             |
| Expertise Mileage:                 | <b>159361</b>                       | Power Kw:    | <b>85</b>                   |
| Bodytype:                          |                                     | Body color:  | <b>Grey</b>                 |
| Gearbox:                           | <b>MAN 6 VIT</b>                    | Paint type:  | <b>Metalic</b>              |
| Transmission:                      | <b>Back</b>                         | Rims summer: | <b>Aluminium</b>            |
| Fueltype:                          | <b>Diesel</b>                       | Oil level:   | <b>OK</b>                   |
| Maintenance:                       | <b>OK</b>                           | Parking lot: | <b>4604</b>                 |
| Maintenance:                       | <b>SERVIVICE IN 24000KM 12 2019</b> |              |                             |
| Battery functioning:               | <b>Yes</b>                          |              |                             |
| Number of doors:                   | <b>5</b>                            |              |                             |
| Number of seats:                   | <b>5</b>                            |              |                             |
| Number head rests:                 | <b>5</b>                            |              |                             |
| Rims summer:                       | <b>Aluminium</b>                    |              |                             |
| Category:                          | <b>Passenger Car</b>                |              |                             |
| Oil level:                         | <b>OK</b>                           |              |                             |
| Registration Certificate Car (BE): | <b>Yes</b>                          |              |                             |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| GPS storage                    | Luggage cover                    |
| GPS storage                    | <b>HD</b> Type of Tow bar        |
| Windows electric F             | <b>Tow bar fixed</b>             |
| Windows electric R             |                                  |
| Steering wheel multifunctional |                                  |
| Radio multimedia               |                                  |
| Type of headlighting           | <b>Headlighting Halogen</b>      |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                         |       |                         |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| <b>205/60/16/96 W LightMetal</b> |       |                         |       |                         |
| Summer tyres:                    | Fr.L. | <b>Vredestein: 5 mm</b> | Fr.R. | <b>Vredestein: 5 mm</b> |
|                                  | Re.L. | <b>Michelin: 6 mm</b>   | Re.R. | <b>Michelin: 5 mm</b>   |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |              |
|-------------------|--------------|
| Total cost ex VAT | <b>63,00</b> |
|-------------------|--------------|

|                                   |             |
|-----------------------------------|-------------|
| Door F L, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

|                               |  |
|-------------------------------|--|
| <i>No pictures to display</i> |  |
|-------------------------------|--|

|  |              |
|--|--------------|
| Bonnet, Dent(s), PDR - Paintless dent repair | <b>63,00</b> |
|--|--------------|



|  |             |
|--|-------------|
| <b>Door F R, Scratch(es), Acceptable</b> | <b>0,00</b> |
| <i>No pictures to display</i>            |             |
| <b>Seat cover F L, Worn, Acceptable</b>  | <b>0,00</b> |
| <i>No pictures to display</i>            |             |
| <b>Bumper R, Scratch(es), Acceptable</b> | <b>0,00</b> |
| <i>No pictures to display</i>            |             |