



BMW 5 BERLINE: 1RXE021

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber: | WBAJC51010G468296 | Versionname: | 520d xDrive (140 kW) Aut. |
| First Registrationdate: | 16/03/2017 | Fiscalpower: | |
| Expertise Mileage: | 36396 | Power Kw: | 140 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | 4 Weel | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4712 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Seats electric F R | |
| Windows electric R | | Seats F L ventilated | |
| Cruise Control | | Seats F R ventilated | |
| Steering wheel multifunctional | | Sun Roof electric | |
| Seats F heated | | Central consol F | |
| Radio multimedia | | Front parking sensors | |
| Type of headlighting | Headlighting LED | Rear parking sensors | |
| Type of GPS | GPS big screen color | Type of Tow bar | No Tow bar |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Head-up Display | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|----------------------|-------|----------------------|
| 245/45/18/100 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Hankook: 5 mm | Fr.R. | Hankook: 5 mm |
| | Re.L. | Hankook: 5 mm | Re.R. | Hankook: 5 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|---|--------------|
| Total cost ex VAT | 63,00 |
| Tailgate, Dent(s), PDR - Paintless dent repair | 63,00 |



| | |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |