



**BMW 3 TOURING: 1LFB568**

Vinnumber:	<b>WBA8J91050K400253</b>	Versionname:	<b>2.0 320D EFFICIENTDYN. (120KW) TOURING</b>
First Registrationdate:	<b>10/09/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>86930</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2115</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

	Runflat	<b>Yes</b>
Total cost ex VAT		<b>1423,86</b>
Wing R R, Scratch(es), LI - Repair and paint (complete)		<b>308,20</b>



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display


Tailgate, Scratch(es), 67 - Polish 0,00

No pictures to display


Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Bonnet, Bad repair, Acceptable

0,00

