



**BMW 4 GRAN COUPE: 1LCD531**

Vinnumber:	<b>WBA4D51040D425261</b>	Versionname:	<b>2.0 418D (100KW) GRAN COUPE</b>
First Registrationdate:	<b>18/08/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>105487</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1415</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/18/91 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

**Assistance equipment**


Number of charging cables (normal)	<b>0</b>	Runflat	<b>Yes</b>
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>495,56</b>
--------------------------	---------------

<b>Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>0,00</b>
--	-------------



Roof, Hail damage, PDR - Hail 0,00



Bonnet, Stone chip(s), Acceptable 0,00

*No pictures to display*

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00







Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Bumper corner R R, Scratch(es), It - Spot repair

115,56





Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00

