



BMW i3: 1LRH424			
Vinnumber:	WBY1Z41040VZ76509	Versionname:	0.6 RANGE EXTENDER ADVANCED AUTOMATIC
First Registrationdate:	13/11/2015	Fiscalpower:	
Expertise Mileage:	12830	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3807
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	155/70/19/84 Q LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment	
Number of charging cables (normal)	1
Total cost ex VAT	2635,79
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02





Fuel tank stopper, Missing, E - Replace

44,00



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Wing R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09

