



BMW i3: 1KFH004			
Vinnumber:	WBY1Z21030V307006	Versionname:	ADVANCED AUTOMATIC
First Registrationdate:	21/04/2015	Fiscalpower:	
Expertise Mileage:	30041	Power Kw:	75
Bodytype:		Body color:	Anthracite
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Electric	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1533
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	155/70/19/84 Q LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment			
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	1853,66
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16



Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
--	---------------



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer R, Crack, Le - Replace and paint

139,27



Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Roof pillar L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16

