



**BMW 2 GRAN TOURER: 1RKZ538**

Vinnumber:	<b>WBA2E310705G36752</b>	Versionname:	<b>1.5 216D GRAN TOURER</b>
First Registrationdate:	<b>17/01/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>135729</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3616</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Sun Roof electric
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	<b>Headlighting Halogen</b>
Type of Lining	<b>GPS big screen color</b>
Type of climate control	<b>Lining leather</b>
	<b>Autom climate control</b>
	<b>Tow bar fixed</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/17/95 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>906,06</b>
-------------------	---------------

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
---	--------------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Backrest cover F R, Tear, E - Replace

195,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s), Acceptable

0,00

*No pictures to display*

Roof pillar L, Dent(s), Acceptable

0,00

*No pictures to display*

Bumper F, Dent(s) and scratch(es), It - Spot repair

115,56



Door panel R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Alloy rim R L polished, Scratch(es), Acceptable

0,00

*No pictures to display*