


BMW X4: 1JXJ947

Vinnumber:	WBAXX110100L93566	Versionname:	2.0 XDRIVE20D (120KW) 4WD
First Registrationdate:	12/03/2015	Fiscalpower:	
Expertise Mileage:	158176	Power Kw:	120
Bodytype:	SUV	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4628
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	245/55/17/102 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1213,98
Tailgate, Scratch(es), 67 - Polish			0,00
<i>No pictures to display</i>			
Bonnet, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Roof, Chemical polution, LI - Repair and paint (complete)			577,80



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16

