



CITROEN C8: 1HJH472

Vinnumber:	VF7EBRHD8EZ020116	Versionname:	C8 Exclusive FAP 136PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	125343	Power Kw:	100
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2306
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Seats F heated		Central consol F	
Type of headlighting	Headlighting Halogen	Luggage cover	
Type of GPS	GPS big screen color	Front parking sensors	
Type of Lining	Lining fabrics	Rear parking sensors	
Type of climate control	Autom climate control	Type of Tow bar	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	764,72
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56





Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Missing, E - Replace	36,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Maintenance book, Missing, E - Replace	0,00
--	------

<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>	
Rear window, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



