



MERCEDES C BREAK: 1JXZ846

Vinnumber:	WDD2052361F170641	Versionname:	1.6 C 180 BLUETEC
First Registrationdate:	17/03/2015	Fiscalpower:	
Expertise Mileage:	103095	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE A IN 171D	Parking lot:	1707
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	SD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	240,00
-------------------	--------


Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Boot carpet, Stain, Cleaning 25,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Repaired, Acceptable 0,00

No pictures to display

Door R R, Repaired, Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Seat cover R R, Stain, Cleaning 25,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Stain, Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display