



PEUGEOT PARTNER: 1L BG571

Vinnumber:	VF37B9HF0FJ740728	Versionname:	1.6 HDI 120 L1H1 66KW PACK GPS
First Registrationdate:	10/08/2015	Fiscalpower:	
Expertise Mileage:	254352	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3201
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 T Steel				
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 4 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	712,28
Bumper R, Scratch(es), Smart repair	110,64



Seat cover F L, Hole, Smart repair

64,32



Wheel cover R R, Scratch(es), E - Replace

22,50



Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)

115,56



Wheel cover F R, Scratch(es), E - Replace

22,50



Bonnet, Dent(s), Acceptable

0,00

No pictures to display


Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Bodywork, Not original part, Acceptable

0,00



Boot carpet, Hole, E - Replace

75,00



Floor covering F L, Worn, Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Scratch(es), Acceptable

0,00

No pictures to display