



**JAGUAR XE: 1LCS245**

Vinnumber:	<b>SAJAB4BN0GA905472</b>	Versionname:	<b>2.0D 163HP AUTO R-SPORT</b>
First Registrationdate:	<b>21/08/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>155403</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1706</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Sun Roof electric	
Steering wheel multifunctional		Central consol F	
Radio multimedia		Front parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>	Type of Tow bar	<b>Tow bar removable</b>
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/17/95 V LightMetal</b>				
Winter tyres:	Fr.L.	<b>Continental: 7 mm</b>	Fr.R.	<b>Continental: 7 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>459,80</b>
-------------------	---------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------





Rearview mirror housing L, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper R, Deformed / Strained, Smart repair 110,64



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Chemical pollution, 67 - Polish 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Ignition key, Worn, Acceptable 0,00

