



CITROEN Jumper 30 SWB: 1GHS478

Vinnumber:	VF7YASMFA12557032	Versionname:	JUMPER 30 B/F SWB L1H1 Fresh (EU5)110PK
First Registrationdate:	11/02/2014	Fiscalpower:	
Expertise Mileage:	146974	Power Kw:	81
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	Yes	Parking lot:	LCV31
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	NOT OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/70/15/109 R Steel				
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2735,83
-------------------	---------

Bumper F L, Scratch(es), Smart repair	110,64
---------------------------------------	--------



Internal Boot Lining L, Broken, Smart repair	110,64
--	--------



Bumper F R, Scratch(es), Smart repair

110,64



Trunk door panel L, Broken, E - Replace

74,00



Trunk door R L, Dent(s), Acceptable

0,00

No pictures to display

Door moulding Lower R L, Missing, E - Replace

91,50



Internal Boot Lining R, Broken, Smart repair

110,64



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Sill outer L, Scratch(es), LI - Repair and paint (complete)

232,88



Wing trim R L, Missing, E - Replace

69,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Interior, Dirty, Cleaning 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door moulding Lower R R, Scratch(es), E - Replace 91,50



Wing F L, Scratch(es), LI - Repair and paint (complete) 165,13



Trunk door R R, Dent(s), It - Spot repair 115,56



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing trim R R, Missing, E - Replace 69,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15





Door F L, Scratch(es), 67 - Polish 0,00

No pictures to display

Rearview mirror L complete, Broken, E - Replace 138,00



Trunk door panel R, Broken, E - Replace 74,00

