



MERCEDES GLA: 1KGK439

Vinnumber:	WDC1569081J113720	Versionname:	2.1 GLA 200 CDI STYLE
First Registrationdate:	28/04/2015	Fiscalpower:	
Expertise Mileage:	65338	Power Kw:	100
Bodytype:		Body color	GRIJS
Gearbox:	MAN 6 VIT	Body color	Dark Grey
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Maintenance	265 DAGEN	Parking lot	2712
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	1		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		
Adaptive cruise control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK





Degree of wear

	215/60/17/96 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		173,64
--------------------------	--	---------------

Door R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), PDR - Paintless dent repair	63,00
	
	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper moulding R Mid, Scratch(es), Smart repair	110,64
	
	
Outer door handle F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	