



CITROEN Berlingo: 1EBC941

Vinnumber:	VF77D9HF8CJ699311	Versionname:	BERLINGO B/F Kort BMP 90PK Aut
First Registrationdate:	9/10/2012	Fiscalpower:	
Expertise Mileage:	104813	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	No	Parking lot:	474
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	NOT OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	No
Tires wear profile	NOT OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	NOT OK	Wiper fluid level	NOT OK
Handbrake	NOT OK	Transmission	NOT OK
		Lighting	NOT OK
		Wiperblades	NOT OK

Degree of wear

	195/65/16/91 W Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1458,16

Seat cover F L, Worn, Acceptable 0,00




Headlight R, Scratch(es), E - Replace 321,00



Roof, Chemical pollution, LI - Repair and paint (complete) 361,13



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Engine, Not functioning (well), Acceptable 0,00



Wheel cover F R, Broken, E - Replace 22,50



Door F R, Dent(s), Acceptable 0,00



Sidewall RL (LCV), Dent(s) and scratch(es), LI - Repair and paint (partial) 361,13



Trunk door R L, Dent(s), PDR - Paintless dent repair 63,00



Wheel cover R L, Scratch(es), Acceptable 0,00



Bumper R, Broken, E - Replace 329,40

