



FORD TRANSIT COURIER: 1TRH104

Vinnumber:	WF0WXXTACWHE65339	Versionname:	1.5 TDCi 56kW Trend
First Registrationdate:	22/01/2018	Fiscalpower:	
Expertise Mileage:	156936	Power Kw:	56
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3304
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/60/15/88 H Steel				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	No
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2168,61
Door panel R L, Broken, E - Replace	91,50



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Roof, Dent(s), LI - Repair and paint (complete) 361,13



Wheel cover F R, Missing, E - Replace 22,50



Spare wheel, Missing, E - Replace 153,60



Backrest cover F L, Hole, Smart repair 64,32



Rocker panel inner F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 22,50



Trunk door R R, Dent(s) and scratch(es), It - Spot repair 115,56



Door panel R R, Broken, E - Replace 91,50



Wheel cover R L, Missing, E - Replace 22,50



Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Missing, E - Replace 22,50



Dashboard, Hole, Smart repair 110,64



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Broken, E - Replace 329,40



Gear shift lever knob, Broken, E - Replace 91,50



Roof pillar R, Dent(s), LI - Repair and paint (complete) 165,14



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Dent(s), Acceptable 0,00

No pictures to display