



**NISSAN Qashqai: 1HKV417**

|                                    |                          |              |                                |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber:                         | <b>SJNFAAJ11U1159763</b> | Versionname: | <b>QASHQAI 2WD Tekna 110PK</b> |
| First Registrationdate:            | <b>13/08/2014</b>        | Fiscalpower: |                                |
| Expertise Mileage:                 | <b>93233</b>             | Power Kw:    | <b>81</b>                      |
| Bodytype:                          | <b>SUV</b>               | Body color:  | <b>Black</b>                   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                 |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3213</b>                    |
| Number of doors:                   | <b>5</b>                 |              |                                |
| Number of seats:                   | <b>5</b>                 |              |                                |
| Number head rests:                 | <b>5</b>                 |              |                                |
| Rims summer:                       | <b>Aluminium</b>         |              |                                |
| Category:                          | <b>Passenger Car</b>     |              |                                |
| Oil level:                         | <b>OK</b>                |              |                                |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                |

**Options**

|                                |                                  |                       |                   |
|--------------------------------|----------------------------------|-----------------------|-------------------|
| Radio CD                       |                                  | Seats electric F L    |                   |
| GPS storage                    | <b>SD</b>                        | Panoramic roof        |                   |
| GPS storage                    |                                  | Central consol F      |                   |
| Windows electric F             |                                  | Luggage cover         |                   |
| Windows electric R             |                                  | Front parking sensors |                   |
| Cruise Control                 |                                  | Rear parking sensors  |                   |
| Steering wheel multifunctional |                                  | Type of Tow bar       | <b>No Tow bar</b> |
| Seats F heated                 |                                  |                       |                   |
| Radio multimedia               |                                  |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>      |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>      |                       |                   |
| Type of Lining                 | <b>Lining artificial leather</b> |                       |                   |
| Type of climate control        | <b>Autom climate control</b>     |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/45/19/96 W LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|                                  | Re.L. | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|  |                |
|--|----------------|
| <b>Total cost ex VAT</b>   | <b>2068,96</b> |
| <b>Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)</b> | <b>95,00</b>   |



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Rocker panel inner R R, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Rocker panel inner R L, Dent(s), Acceptable 0,00

No pictures to display

Door seal R, Deformed / Strained, E - Replace 54,00



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Stone chip(s), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08





Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00



Boot cover, Broken, E - Replace 50,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Inner seat cover L, Broken, Smart repair 110,64

