



**PEUGEOT 308 SW: 1JGP534**

Vinnumber:	<b>VF3LC9HPAES287091</b>	Versionname:	<b>308 SW Access 92PK</b>
First Registrationdate:	<b>12/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>160052</b>	Power Kw:	<b>68</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>17.100 KM</b>	Parking lot:	<b>4202</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	Type of Tow bar
Cruise Control	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>No GPS</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 T Steel</b>				
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>1449,39</b>
--------------------------	----------------

<b>Rearview mirror housing L, Scratch(es), Acceptable</b>	<b>0,00</b>
---	-------------

*No pictures to display*

<b>Wheel cover F R, Scratch(es), E - Replace</b>	<b>30,00</b>
--	--------------



<b>Door F L, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

No pictures to display

Grill, Broken, E - Replace

158,68



Wheel cover R R, Scratch(es), E - Replace

30,00



Door R L, Dent(s), Acceptable

0,00

No pictures to display

Front compartment engine mounting, Tear, E - Replace

69,71



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer L, Dent(s), LI - Repair and paint (complete)

406,50



Headlight R, Scratch(es), E - Replace

396,00



Sill outer R, Dent(s), LI - Repair and paint (complete)

358,50

