



## VOLKSWAGEN Polo: 1GRY603

Vinnumber:	<b>WVWZZZ6RZEY243337</b>	Versionname:	<b>POLO BlueMotion Techn.DPF 90PK</b>
First Registrationdate:	<b>11/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>110666</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3713</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

<b>185/60/15/84 H Steel</b>				
Summer tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Kleber: 5 mm</b>	Re.R.	<b>Kleber: 5 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	815,26
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Wheel cover R L, Scratch(es), Acceptable	0,00



Wheel cover R R, Scratch(es), E - Replace

24,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06



Roof, Dent(s), LI - Repair and paint (complete)

385,20



Bumper corner R L, Scratch(es), Acceptable

0,00



Wheel cover F L, Scratch(es), Acceptable

0,00



Bonnet, Bad repair, Acceptable

0,00



Wheel cover F R, Scratch(es), E - Replace

24,00



Door R R, Repaired, Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

