



VOLKSWAGEN Crafter 35 LWB: 1BRG765

Vinnumber:	WV1ZZZ2FZB7005321	Versionname:	CRAFTER 35 PU2C LWB 109PK
First Registrationdate:	11/08/2011	Fiscalpower:	
Expertise Mileage:	166445	Power Kw:	80
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	4		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/16/115 R Steel				
Summer tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2319,55
-------------------	----------------

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	165,13
---	---------------





Sill outer L, Scratch(es), LI - Repair and paint (complete)

232,88



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Seat cover F L, Damaged, E - Replace

300,00



Door R L, Rust, LI - Repair and paint (complete)

238,76



Rearview mirror housing R, Broken, E - Replace

20,00



Door R R, Rust, LI - Repair and paint (complete)

238,76



Bonnet, Deformed / Strained, Le - Replace and paint

780,50



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Bumper F, Scratch(es), Smart repair

110,64

