



**OPEL Mokka: 1FLQ498**

Vinnumber:	<b>W0LJC7EL1DB172618</b>	Versionname:	<b>MOKKA ecoFLEX 4x2 Enjoy 130PK</b>
First Registrationdate:	<b>8/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>113015</b>	Power Kw:	<b>96</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2724</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/55/18/95 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------


Total cost ex VAT 1328,82

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)

115,56




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

290,08

