



**RENAULT Megane: 1HJV540**

Vinnumber:	<b>VF1KZ140651346576</b>	Versionname:	<b>MEGANE GT Energy Business 110PK</b>
First Registrationdate:	<b>5/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>143142</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1315</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H Steel</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 1056,26

Door R R, Dent(s) and scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F M, Scratch(es), Acceptable 0,00

*No pictures to display*

Protection plate M, Deformed / Strained, E - Replace

0,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete)

115,56



Windscreen, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Chemical polution, LI - Repair and paint (complete)

308,20



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Smart repair

110,64



Rear window, Scratch(es), Acceptable

0,00



Bonnet, Chemical polution, Acceptable

0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

301,68

