



VOLKSWAGEN Crafter 35 MWB: 1ATZ855

Vinnumber:	WV1ZZZ2FZB7005370	Versionname:	CRAFTER 35 LB2C MWB 109PK
First Registrationdate:	23/03/2011	Fiscalpower:	
Expertise Mileage:	165213	Power Kw:	80
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV11
Number of doors:	4		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Type of Tow bar	Tow bar fixed
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/16/113 R Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1611,35
Centre console, Broken, E - Replace	108,00





Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Dent(s), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,13



Switch window control F L, Broken, E - Replace 74,00



Seat cover F R, Worn, Acceptable 0,00

No pictures to display

Bumper F, Crack, E - Replace 398,40



Door R R, Rust, Acceptable 0,00

No pictures to display

Door R L, Rust, LI - Repair and paint (complete) 238,76



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Hole, E - Replace 300,00



Rearview mirror glass R, Broken, E - Replace 13,50



Bonnet, Dent(s), LI - Repair and paint (complete) 313,56

