



**VOLKSWAGEN Crafter 35 MWB: 1BEM253**

Vinnumber:	<b>WV1ZZZ2FZB7005534</b>	Versionname:	<b>CRAFTER 35 LB2C MWB 109PK</b>
First Registrationdate:	<b>12/05/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>224376</b>	Power Kw:	<b>80</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV15</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>No climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/65/16/121 R Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 8 mm</b>	Fr.R.	<b>Continental: 8 mm</b>
	Re.L.	<b>Bridgestone: 7 mm</b>	Re.R.	<b>Bridgestone: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
Total cost ex VAT	<b>2701,47</b>
Bumper F, Scratch(es), Smart repair	<b>110,64</b>





Boot carpet, Hole, E - Replace

75,00



Door R R, Rust, Le - Replace and paint

746,18



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Backrest cover F L, Damaged, E - Replace

300,00



Seat cover F L, Damaged, E - Replace

300,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13



Sill outer L, Scratch(es), LI - Repair and paint (complete)

232,88



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76





Seat cover F R, Damaged, E - Replace

300,00

