


RENAULT Scenic: 1KF910

Vinnumber:	VF1JZ14K652396208	Versionname:	SCENIC Energy Life 110PK
First Registrationdate:	24/04/2015	Fiscalpower:	
Expertise Mileage:	105457	Power Kw:	81
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3312
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H Steel				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2225,46
Seat cover R R, Stain, Cleaning	25,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror R complete, Broken, E - Replace 168,00



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Headrest R M, Missing, E - Replace 60,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 553,50



