



## VOLKSWAGEN Sharan: 1GSD284

Vinnnummer:	<b>WVWZZZ7NZEVO27491</b>	Versionname:	<b>SHARAN Comfortline BMT 136PK</b>
First Registrationdate:	<b>14/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>105706</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3602</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

<b>215/60/16/95 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>2464,69</b>
Roof, Chemical polution, LI - Repair and paint (complete)	<b>577,80</b>



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Sliding door R, Scratch(es), LI - Repair and paint (complete)

522,85



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Scratch(es), E - Replace

0,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Door F L, Dent(s) and scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16

