



BMW 1 HATCH: 1KPK329

Vinnumber:	WBA1V910905B15952	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	9/06/2015	Fiscalpower:	
Expertise Mileage:	76442	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2112
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2506,33
Wing F R, Chemical polution, LI - Repair and paint (complete)	220,18




Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bad repair, Acceptable 0,00



Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, Acceptable 0,00

No pictures to display


Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35




Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Hole, Le - Replace and paint

735,00



Door F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer L, Scratch(es), LI - Repair and paint (complete)

310,50



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Rear wiper arm, Incomplete, E - Replace

20,00

