



BMW 3 TOURING: 1KTP296

Vinnumber:	WBA3K11040F840465	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	1/07/2015	Fiscalpower:	
Expertise Mileage:	148683	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2623
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	NOT OK

Degree of wear


	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	404,08
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	290,08





Windscreen, Stone chip(s), Acceptable 0,00



Rear wiper arm, Missing, E - Replace 74,00



Rear wiper blade, Missing, E - Replace 40,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display