



BMW 2 GRAN TOURER: 1NTL462

Vinnumber:	WBA2E71040P935205	Versionname:	2.0 220D (140KW) GRAN TOURER
First Registrationdate:	22/04/2016	Fiscalpower:	
Expertise Mileage:	203937	Power Kw:	140
Bodytype:	MPV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3215
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/17/91 W LightMetal			
Summer tyres:	Fr.L. Goodyear: 5 mm	Fr.R. Goodyear: 5 mm	
	Re.L. Michelin: 5 mm	Re.R. Michelin: 5 mm	

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	430,00
-------------------	---------------

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door panel R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Luggage space cover, Not functioning (well), E - Replace	240,00
--	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

