



BMW 3 GRAN TURISMO: 1LBX609

Vinnumber:	WBA3Y110X0GD88288	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	14/08/2015	Fiscalpower:	
Expertise Mileage:	161668	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2633
Maintenance:	30000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	928,20
-------------------	---------------

Door F L, Scratch(es), 67 - Polish	0,00
------------------------------------	-------------



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F L, Scratch(es), Acceptable 0,00



Door R R, Scratch(es), 67 - Polish 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), 67 - Polish 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing L, Scratch(es), Acceptable 0,00



Ignition key, Worn, Acceptable 0,00



Interior, Dirty, Cleaning 100,00





Bumper F, Scratch(es), Acceptable 0,00



Door F R, Scratch(es), 67 - Polish 0,00



Backrest cover F L, Worn, Acceptable 0,00

