



BMW 3: 1JAL532

Vinnumber:	WBA3Y11000D450859	Versionname:	3 GRAN TURISMO 318d 136PK
First Registrationdate:	18/11/2014	Fiscalpower:	
Expertise Mileage:	127690	Power Kw:	100
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2120
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	138,00
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, Acceptable	0,00

No pictures to display

Engine protective plate, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover F L, Damaged, Acceptable	0,00
-------------------------------------	------

No pictures to display

Foglight R, Broken, E - Replace	138,00
---------------------------------	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tailgate, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display