



BMW 5 TOURING: 1KSC986

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber: | WBA5L31040G081165 | Versionname: | 2.0 520D (140KW) TOURING |
| First Registrationdate: | 22/06/2015 | Fiscalpower: | |
| Expertise Mileage: | 114918 | Power Kw: | 140 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2611 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--|
| Radio CD | | Seats electric F L | |
| GPS storage | | Seats electric F R | |
| GPS storage | HD | Sun Roof electric | |
| Windows electric F | | Panoramic roof | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Luggage cover | |
| Steering wheel multifunctional | | Front parking sensors | |
| Seats F heated | | Rear parking sensors | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 245/45/18/96 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |

Assistance equipment

| | |
|---------|------------|
| Runflat | Yes |
|---------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 248,80 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|-------------------------------|-------------|
| Wing R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display

| | |
|---|--------------|
| Alloy rim R R polished. Scratch(es). LI - Repair and paint (complete) | 95,00 |
|---|--------------|



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair

58,80



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display