



FORD GRAND C-MAX: 1JNF300

Vinnumber:	WFOHXXGCBHEG67686	Versionname:	1.6 TDCI 85KW S/S TREND STYLE
First Registrationdate:	23/01/2015	Fiscalpower:	
Expertise Mileage:	162704	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Body color	GRIS
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	2614
Number of seats	7		
Number head rests	6		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 2 mm	Re.R.	Continental: 2 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	802,38
-------------------	---------------

Alloy rim F R polished, Rust, Acceptable	0,00
--	-------------

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bonnet, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

No pictures to display

Outer door handle R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R R, Dent(s), Acceptable	0,00
---	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Backrest cover F R, Tear, Acceptable	0,00
--------------------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door panel R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Seat cover F R, Tear, Acceptable	0,00
----------------------------------	------

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Windscreen, Stone chip(s), E - Replace	487,20
--	--------



Door F R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Centre console, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R polished, Rust, Acceptable	0,00
<i>No pictures to display</i>	