



**FORD KUGA: 1KXX747**

Vinnumber:	<b>WF0AXXWPMFY52076</b>	Versionname:	<b>2.0 TDCI 2WD 110KW TITANIUM</b>
First Registrationdate:	<b>28/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>138438</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1331</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/55/17/103 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 2 mm</b>	Fr.R.	<b>Kleber: 2 mm</b>
	Re.L.	<b>Kleber: 3 mm</b>	Re.R.	<b>Kleber: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>608,22</b>
--------------------------	---------------

<b>Alloy rim F L, Scratch(es), Acceptable</b>	<b>0,00</b>
---	-------------

*No pictures to display*

<b>Bonnet, Stone chip(s), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Door R L, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler R, Scratch(es), It - Spot repair 115,56



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Chemical polution, Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Smart repair 110,64



Door F L, Scratch(es), Acceptable 0,00

No pictures to display