



**PEUGEOT 5008: 1FUN477**

Vinnumber:	<b>VF30E9HD8DS180820</b>	Versionname:	<b>5008 e-HDi Active FAP BMP 115PK Aut.</b>
First Registrationdate:	<b>29/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>104089</b>	Power Kw:	<b>84</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV04</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>
	<b>No Tow bar</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>NOT OK</b>

**Degree of wear**

<b>215/55/16/93 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Semperit: 6 mm</b>	Fr.R.	<b>Semperit: 6 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	3978,74
Rearview mirror R complete, Broken, Le - Replace and paint	283,00





Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 50,00



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear wiper blade, Missing, E - Replace 20,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80





Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rearview mirror L complete, Scratch(es), Le - Replace and paint

283,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35





Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

301,68



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Deformed / Strained, LI - Repair and paint (complete)

220,18

