



MERCEDES C BREAK: 1NSK794

Vinnumber:	WDD2052041F371317	Versionname:	2.1 C 220 D 120KW AMG LINE
First Registrationdate:	15/04/2016	Fiscalpower:	
Expertise Mileage:	174651	Power Kw:	120
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2732
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/40/18/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	190,00
-------------------	---------------

Bumper F, Stone chip(s), Acceptable	0,00
-------------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), 67 - Polish	0,00
------------------------------------	-------------

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

