



MERCEDES GLA: 1KXV362

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber: | WDC1569081J167647 | Versionname: | 2.1 GLA 200 CDI URBAN |
| First Registrationdate: | 28/07/2015 | Fiscalpower: | |
| Expertise Mileage: | 126155 | Power Kw: | 100 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3128 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 1 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | HD | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 235/50/18/97 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Vredestein: 7 mm | Fr.R. | Vredestein: 7 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment



| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

Total cost ex VAT 730,11

Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

| | | |
|--|--|--------|
| <i>No pictures to display</i> | | |
| Door R L, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Wing R L, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Door R R, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) | | 348,09 |
|  | | |
| Wing F R, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Wing R R, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) | | 382,02 |
|  | | |
| Bumper F, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Roof, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |