



<b>MINI : 1HKT005</b>			
Vinnumber:	<b>WMWXN110103A01113</b>	Versionname:	
First Registrationdate:	<b>12/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>61617</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2233</b>
Number of doors:	<b>3</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Windows electric F		Luggage cover	
Radio multimedia		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
<b>175/65/15/84 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Hankook: 5 mm</b>	Re.R.	<b>Hankook: 5 mm</b>

<b>Assistance equipment</b>	
Repair kit	<b>Yes</b> Compressor <b>Yes</b>
Total cost ex VAT	632,44
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bodywork, Not original part, Acceptable	0,00
---	------

*No pictures to display*

Aerial, Broken, E - Replace	15,00
-----------------------------	-------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Wing F L, Scratch(es), It - Spot repair	115,56
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Roof, Dent(s), Acceptable	0,00
---------------------------	------

*No pictures to display*