



MERCEDES A: 1LCE779

Vinnumber:	WDD1760121V091659	Versionname:	1.5 A 180 CDI
First Registrationdate:	18/08/2015	Fiscalpower:	
Expertise Mileage:	56597	Power Kw:	80
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3322
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

195/65/15/91 T Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1693,13
Rear window, Scratch(es), E - Replace	0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover F L, Missing, E - Replace

30,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wheel arch cover F L, Broken, E - Replace

81,48



Wheel cover F R, Scratch(es), E - Replace

30,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Repaired, Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00



Wheel cover R L, Scratch(es), E - Replace 30,00

