



MINI ONE: 1PGX313

Vinnumber:	WMWXN110803A01111	Versionname:	
First Registrationdate:	12/10/2014	Fiscalpower:	
Expertise Mileage:	135520	Power Kw:	70
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2122
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Luggage cover	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

175/65/15/94 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment





Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1490,88

Bumper grille, Crack, E - Replace 64,00



Bodywork, Not original part, Acceptable 0,00

Wing R L 3P, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s), LI - Repair and paint (complete)	211,80
	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	290,08
	
Bumper F, Crack, Le - Replace and paint	735,00
	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
