


RENAULT Kangoo: 1DOE512

Vinnnumber:	VF1KW25B547565020	Versionname:	KANGOO 2PLC Expression FAP 90PK
First Registrationdate:	5/07/2012	Fiscalpower:	
Expertise Mileage:	161128	Power Kw:	66
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3524
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Dunlop: 2 mm	Fr.R.	Dunlop: 2 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 768,35

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Wheel covers R,R, Scratch(es), E - Replace 20,00

wheel cover R R, Scratch(es), E - Replace

30,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Scratch(es), Acceptable

0,00

No pictures to display

GPS, Not functioning (well), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

30,00



Luggage space cover, Missing, E - Replace

240,00



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Deformed / Strained, Acceptable

0,00

No pictures to display

Door F R, Dent(s), LI - Repair and paint (complete)

318,35

