



PEUGEOT BOXER: 1JSB977

Vinnumber:	VF3Y8TMFA12783452	Versionname:	333 L1H2 2.2 HDI 130 PACK CD-AIRCO
First Registrationdate:	11/02/2015	Fiscalpower:	
Expertise Mileage:	217792	Power Kw:	96
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV20
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/70/15/109 R Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1153,03
Rearview mirror R complete, Broken, E - Replace	138,00



Rearlight R , Broken, E - Replace	91,50
-----------------------------------	--------------



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair 63,00



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Ignition key, Missing, E - Replace 150,00



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 361,13



Bumper R, Crack, Smart repair 110,64



Interior, Dirty, Cleaning 0,00

