



**TOYOTA YARIS: 1KGR610**

Vinnumber:	<b>VNKKD3D310A155130</b>	Versionname:	<b>1.5 VVT-I HYBRID COMFORT AUTO</b>
First Registrationdate:	<b>29/04/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>14230</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3231</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F		Luggage cover	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>175/65/15/84 H Steel</b>				
Summer tyres:	Fr.L.	<b>Dunlop: 5 mm</b>	Fr.R.	<b>Dunlop: 5 mm</b>
	Re.L.	<b>Dunlop: 7 mm</b>	Re.R.	<b>Dunlop: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>0,00</b>
Door F L, Bad repair, Acceptable	<b>0,00</b>





Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Bad repair, Acceptable	0,00
------------------------------	------



Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	0,00
---	------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Wing R L, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Bad repair, Acceptable	0,00
----------------------------------	------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display