



**VOLVO XC60: 1LDZ566**

Vinnumber:	<b>VV1DZARC1G2814920</b>	Versionname:	<b>2.0 D3 2WD MOMENTUM</b>
First Registrationdate:	<b>1/09/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>131064</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2808</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>Tow bar removable</b>
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**


Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/17/108 V LightMetal</b>			
Summer tyres:	Fr.L. <b>Uniroyal: 2 mm</b>	Fr.R. <b>Uniroyal: 2 mm</b>	
	Re.L. <b>Pirelli: 6 mm</b>	Re.R. <b>Pirelli: 6 mm</b>	

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>751,86</b>
Bumper R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			<b>382,02</b>



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, Acceptable 0,00

